




*FIG. 1*



*FIG. 2*



*FIG. 3*



*FIG. 4*






FIG. 5



*FIG. 6*



*FIG. 7*

0	0	0
0	1	0
0	0	0


*FIG. 8*

0	1/6	0
1/6	1/3	1/6
0	1/6	0

*FIG. 9*

1/8	1/8	0
1/8	1/4	1/8
0	1/8	1/8


*FIG. 10*




*FIG. 11*

0	0	0
0	$1/4$	$1/4$
0	$1/4$	$1/4$


*FIG. 12*



*FIG. 13*



**FIG. 14**



*FIG. 15*







FIG. 16



*FIG. 17*



*FIG. 18*



*FIG. 19*






FIG. 20





*FIG. 21*

S105



*FIG. 22*



*FIG. 23*

751




FIG. 24





FIG. 25



*FIG. 26*

0	0	0	0	0
0	0	0	0	0
1/5	1/5	1/5	1/5	1/5
0	0	0	0	0
0	0	0	0	0

*FIG. 27*




*FIG. 28*




*FIG. 29*

*FIG. 30.*


S105



*FIG. 31*



*FIG. 32*



*FIG. 33*




FIG. 34







FIG. 35




*FIG. 36*




*FIG. 37*



*FIG. 38*




*FIG. 39*




*FIG. 40*

0	0	0	0	0
$\frac{1}{5}$	$\frac{1}{5}$	0	0	0
0	0	$\frac{1}{5}$	0	0
0	0	0	$\frac{1}{5}$	0
0	0	0	0	$\frac{1}{5}$


FIG. 41



*FIG. 42*



*FIG. 43*



60




FIG. 44